

दिल्ली शहरी आश्रय सुधार बोर्ड  
राष्ट्रीय राजधानी क्षेत्र दिल्ली सरकार


क्रमांक: एफ-03/पी.सी./ए.क्यू.सी.26/370-12

दिनांक: 16/03/18

विषय :- श्री महेन्द्र यादव द्वारा दिल्ली विधानसभा में उठाये गए तारांकित प्रश्न संख्या 26 का उत्तर।

प्रश्न	उत्तर
(क) ओ/एम ( परिचालन एवं रख-रखाव की वर्तमान स्थिति जानने हेतु डीयूएस आई बी में उच्च स्तर पर कितने निरीक्षण किए गए हैं, इन सभी निरीक्षणों के मिनिट्स उपलब्ध कराए जाएं।	सी0ई0ओ0 डीयूएसआईबी द्वारा दिये गये निर्देशों पर समय-समय पर उच्च अधिकारी निरीक्षण करते रहें हैं उसके मिनिट्स जारी नहीं किये जाते हैं। अभी हाल में सी0ई0ओ0, मेम्बर (इंजिनियरिंग), सी0ई0 ने 7 दिन तक निरीक्षण किया था। उसकी रिपोर्ट संलग्न है।
(ख) जनता के लाभ हेतु टॉयलेट कम्पलैक्स के समुचित उपयोग की जानकारी के लिए डीयूएसआईबी द्वारा अब तक कितने जागरूकता कार्यक्रम आयोजित किए गए हैं।	यह कार्यक्रम एन0जी0ओ0 द्वारा किये गये हैं व जिनकी जानकारी अभी उपलब्ध नहीं है। सभी शौचालयों में उचित जानकारी के बोर्ड लगाये गये हैं।
(ग) यदि संख्या 1से 10 के बीच तय किया जाए तो डीयूएसआईबी के शौचालय परिसरों एवं अन्य परिसम्पत्तियों हेतु ओ / एम (परिचालन एवं रख-रखाव,) का न्यूनतम संतोषजनक स्तर क्या है, और	डीयूएसआईबी द्वारा ऐसी कोई स्टडी या ऐसेसमेंट नहीं किया गया है अतः यह अनुमान लगाना सम्भव नहीं है।
(घ) पिछले 5 वर्षों में डीयूएसआईबी के ओ/ एम (परिचालन एवं रख-रखाव) के स्तर की वर्तमान स्थिति क्या है।	सभी शौचालयों में पानी बिजली व रख-रखाव ऐजेंसी उपलब्ध हैं एवं रख-रखाव का स्तर सन्तोष जनक है।

यह उत्तर सक्षम अधिकारी की पूर्व अनुमति से प्रेषित किया जाता है।

  
उप निर्देशक (संसद कक्षा)

उप सचिव (.वि.श), दिल्ली सचिवालय, दिल्ली सरकार



<p>5</p>	<p>Observations : One no. door in gents section of toilet complex found dislodged. Few people stated that the complex not remain open in the night after 11:00 PM to 4:00 AM.. Mixed views were received in r/o frequency of cleanliness as some people viewed that the frequency is not adequate whereas few showed their satisfaction towards the frequency of cleanliness. Some ladies told that the caretaker does not allow small kids to use the toilet complex without accompanny of some elder one.</p> <p>Action : The dislodged door shall be repaired within two days. The show cause notice has been issued to the existing O &amp; M agency in r/o observations as above.</p>
<p>6</p>	<p>In addition to above issues, it was learnt that women from the nearby jhuggis existing had to defecate in the open on a naallah. These were regarding the 40 nos. of jhuggies existing adjoining central warehouse opposite state bank colony GTK road. It was decided that the concerned staff of C-7 alongwith area MLA will inspect and Identify the land for providing toilet facility and ascertain the feasibility for providing the toilets.</p> <p>Apart from above, it was informed by O&amp;M agency and caretaker of the complexes showing general security concern during night hours where very few people visit the toilet and as a safe guard caretaker open the gates as and when local jhuggi dwellers knock the gate of the complex.</p> <p>In general toilet complexes are being cleaned thoroughly during non peak hours and directions have been issued to do cleaning at regular intervals for better maintenance and cleanliness of the toilets.</p>

Delhi Urban Shelter Improvement Board

Inspection report of visit to toilet complexes in Timarpur area on 12.02.2018

Sr. No.	Div.	AC-No.	JSC Code	Location	No. of seats	Type of building	Sewer Line/ Septic tank	O & M agency	Water	Lightning	Cleanliness	Display board	Drainage	O & M	Fixtures
1	C-7	3	3CJ1058	Sanjay Basti Timarpur behind BVK	35	Pucca	SL	M/s Delhi Paryavar an Vikas Samiti	Available	available	Satisfactory	Available	Available	Satisfactory	Available
<p><b>Observations :</b> The Hon'ble Chair Person DCW informed that some unlaful activities like illegal sale of liquor have been reported by the JJ dwellers. The room of the caretaker was searched by the beat constable called through call on 100. During search, some liquor bottles were found by the PCR ASI Sh. Pooran Prakash.</p> <p><b>Action :</b> Show cause notice is being issued to the O &amp; M agency. Cognizance has been taken by Delhi Police for further action in this matter for action against the defaulter.</p>															
2	C-7	3	3CJ1002	Sanjay Basti Timarpur (Lower portion)	20	Pucca	SL	M/s Delhi Paryavar an Vikas Samiti	Available	Available	Satisfactory	Available	Available	Satisfactory	Available
<p><b>Observations :</b> The over all complex was satisfactory however Hon'ble chairperson DCW desired to improve the cleanliness. Some of the local residents pointed out that complex does not open during late night hours. Whereas some of the residents were of the opinion that the complex should remain closed during late night hours due to law &amp; order issues.</p> <p><b>Action :</b> O &amp; M agency has been asked to improve the cleanliness in the complex and the complex be kept open round the clock . In case of law &amp; order issue the local police help may be sought by the O &amp; M agency.</p>															
3	C-7	3	3CJ1003	Sanjay Basti Balak Ram Hospital Road	20	Pucca	SL	M/s Delhi Paryavar an Vikas Samiti	Available	Available	Satisfactory	Available	Available	Satisfactory	Available

**Observations :** The over all complex was satisfactory however Hon'ble chairperson DCW desired to improve the cleanliness. 1 no. bicycle was found lying abandoned in ladies section and 2 nos. bath rooms are converted into store.

**Action :** O & M agency has been asked to improve the cleanliness in the complex. The bicycle was got removed during the inspection itself. Concerned Ex. Engineer has been directed to get the bath rooms vacated and be made functional within a week time.

(14)

4	C-7	3	3CJ 1004	Shyam Basti Timarpur	24	Pucca	SL	No	Available	Available (Local arrangement by JJ dwellers)	Not satisfactory	Available	Available	By local residents	Available
---	-----	---	----------	----------------------	----	-------	----	----	-----------	--	------------------	-----------	-----------	--------------------	-----------

**Observations :** The toilet complex was not functional by DUSIB due to non-availability of electric connection due to pending arrears of MCD time. However the local residents started using the complex by making temporary arrangement of electricity from the nearby jhuggi.

**Action :** The electric connection, which has already been applied by DUSIB, is being pursued with TPDDL and is expected to be fixed shortly.

P.S; Videography has also been done and the record is available in DUSIB office.

**Delhi Urban Shelter Improvement Board  
Inspection Report of visit to Toilet Complexes in AC-51 Kalka Ji Area on 13.02.2018**

An inspection of toilet complexes of DUSIB was carried out by CEO, DUSIB alongwith Dr. Fraheen Malick, Member DCW and other officers of DUSIB.

S.No	Div.	AC. No	Code of JSC	Location	No of Seats	Type of Building	SL/ST	O & M agency	Water	Lighting	Cleanliness	Disp Board	Drainage	O&M	Fixtures
1	C06	51	51CJ0837	JJ Basti Bhoomiheen Camp	185	Pucca	SL	M/s Bhartiya Manoj Sewa Sansthan	Available	available	satisfactory	available	available	available	available
<p>Observations : The complex was overall satisfactory. The large number of user were found at the time of inspection and the complex was almost over crowded being peak hours. The JJ Dwellers and the care taker informed that around 5000 persons are using this toilet block daily. The complex remains open round the clock.</p> <p align="center">Action : The O&amp;M agency has been directed to maintain more cleanliness during peak hours.</p>															
2	C06	51	51CJ0840	JJ Basti Nehru Navjeevan Camp	79	Pucca	SL	M/s Bhartiya Manoj Sewa Sansthan	Available	available	satisfactory	available	available	available	available
<p>Observations : The complex was overall satisfactory however, Member, DCW desired to improve the cleanliness in the complex during peak hours. Approximately 2500 users are using this complex daily. Some of the female JJ Dwellers informed the Member, DCW that in ladies section the locking arrangement inside the WCs is not working properly.</p> <p align="center">Action : The O&amp;M agency has been directed to maintain more cleanliness during peak hours. The area EE has been directed to take immediate action to rectify the locking arrangement from inside in all the WCs.</p>															

(12)

## Inspection Report of visit to Toilet Complexes in AC-51 Kalka Ji Area on 13.02.2018

An inspection of toilet complexes of DUSIB was carried out by CEO, DUSIB alongwith Dr. Fraheen Malick, Member DCW and other officers of DUSIB.

S.No	Div.	AC. No	Code of JSC	Location	No of Seats	Type of Building	SL/ST	O & M agency	Water	Lighting	Cleanliness	Disp Board	Drainage	O&M	Fixtures
3	C06	51	51CJ0839	JJ Basti Nehru Navjeevan Camp	23	Pucca	SL	M/s Bhartiya Manoj Sewa Sansthan	Available	available	satisfactory	available	available	available	available
<p>Observations : The complex was overall satisfactory. Approximately 700 users are using this complex daily. Some of the female JJ Dwellers informed the Member, DCW that in ladies section the locking arrangement inside the WCs is not working properly. In some WCs, the light points were not found functional. 4 nos. WCs in ladies section were reported choked at the time of inspection.</p> <p style="text-align: center;">Action : The area EE has been directed to take immediate action to rectify the locking arrangement from inside in all the WCs. CEO, DUSIB desired that locking arrangement in WCs in ladies section be checked and same may be made perfect in all the toilet block wherever required. EE (Elect.) was directed to rectify the defects of electric points in the WCs. EE C-6 has been directed to take immediate action to clear the choked WCs in ladies section today itself.</p>															
4	C 06	51	51CJ0835	JJ Basti Bhoormiheen Camp	33	Pucca	SL	M/s Bhartiya Manoj Sewa Sansthan	Available	available	satisfactory	available	available	available	available
<p>Observations : The sewerline pertaining to DJB outside the toilet complex was overflowing and filthy water was accumulated at the entry of the Jan Suvidha Complex. Member, DCW desired to improve the cleanliness in the complex. The JJ Dwellers informed that the complex is open round the clock and approximately 1000 users are using this complex daily.</p> <p style="text-align: center;">Action : The area EE, DUSIB informed that matter of choked sewer line outside the complex has already been taken up with DJB for cleaning of sewerline. CEO, DUSIB directed that matter may kindly be taken up at higher level in DJB if the complaint not attended today. O&amp;M Agency has been directed to improve the cleanliness in the complex in view of mixed reaction of the JJ Dwellers towards cleanliness. EE C-6 has been directed to take necessary action in the matter.</p>															
5	<p>Suggestion : Member, DCW, (Dr. Fraheen Malick) also suggested that DCW through their Mahilla Panchayat Programme will educate women about sanitary napkin disposal through Mahilla Panchayat's Community meetings to avoid choking, as it was told by some ladies there that ladies dispose sanitary napkins in the toilets.</p>														

P.S.: The videography of the inspection carried out of the toilet complexes as mentioned above has been done and the record is available in DUSIB office.

Delhi Urban Shelter Improvement Board

Inspection Report of visit to Toilet Complexes in AC-17 Wazirpur Area on 14.02.2018

An inspection of toilet complexes of DUSIB was carried out by Chief Engineer (Coordn.), DUSIB alongwith Ms. Sarika Chaudhary, Member DCW and other officers of DUSIB.

S.No	Div.	AC. No	Code of JSC	Location	No of Seats	Type of Building	SL/ST	O & M agency	Water	Lighting	Cleanliness	Disp Board	Drainage	O&M	Fixtures
1	C04	17	17CJ0415	Sawan Park, Chowki No. 3(JSC No 2)	54	Pucca	SL	M/s H K Professional Pvt Ltd	Available	available	satisfactory	available	available	available	available
<p>Observations : Since the renovation work was in progress. The complex was not cleaned properly due to ongoing repair work .The broken doors are also being replaced.</p> <p>Action : The O&amp;M agency has been directed to maintain more cleanliness during peak hours. EE has been directed to get the work expedited immediately for proper functioning and cleanliness of the complex</p>															
2	C04	17	17CJ0414	Sawan Park, Chowki No. 3(JSC No 1)	40	Pucca	SL	No O&M agency deployed by DUSIB	N/A	N/A	N/A	N/A	N/A	N/A	N/A
<p>Observations : DUSIB has officially closed this complex as MLA has desired to construct a Community hall in place of this abandoned toilet. However, the complex was forcefully run by local public as DUSIB has not deployed any O&amp;M agency. It was alleged by the public that Rs 2/- is beng charged by the person manning the complex.</p> <p>Action : EE has been directed to close the entry of JSC by erecting wall at the entry of the complex to avoid any misuse.</p>															



**Inspection Report of visit to Toilet Complexes in AC-17 Wazirpur Area on 14.02.2018**

An inspection of toilet complexes of DUSIB was carried out by Chief Engineer (Coordn.), DUSIB alongwith Ms. Sarika Chaudhary, Member DCW and other officers of DUSIB.

S.No	Div.	AC. No	Code of JSC	Location	No of Seats	Type of Building	SL/ST	O & M agency	Water	Lighting	Cleanliness	Disp Board	Drainage	O&M	Fixtures
3	C04	17	17CJ0411	J1-J2, Block Wazirpur JJ Colony (Site-I)	20	Pucca	SL	M/s H K Professional Pvt Ltd	Available	available	satisfactory	available	available	available	available
<p>Observations : The complex was recently taken over from North MCD and repair work could not be taken up due to non availability of funds under Revenue Head.</p>															
<p>Action : EE has been directed to immediately take up repair work as a interim measures from the available funds till upgradation/renovation is taken up.</p>															
4	C04	17	17CJ0410	K Block Wazirpur JJ Colony	29	Pucca	SL	M/s H K Professional Pvt Ltd	Available	available	satisfactory	available	available	available	available
<p>Observations : Member , DCW found acid stored in the ladies section and police was called to seize the same. Some Rickshaw and bikes were parked in the toilet complex.</p>															
<p>Action : EE has been directed to issue show cause notice to the agency. He has also been directed to remove all the rickshaw/bikes found parked in the complex and necessary steps be taken to avoid such incident again.</p>															
5	C04	17	17CJ0498	K & L-Block, Wazirpur JJ Colony	28	Pucca	SL	M/s H K Professional Pvt Ltd	Available	available	satisfactory	available	available	available	available
<p>Observations : Some seats at first floor were found choked. some doors needs repairs. Member DCW raised the issue of unsatisfactory cleanliness in the complex</p>															
<p>Action : The complex was recently taken over from North MCD and repair work could not be taken up due to non availability of funds under Revenue Head in DUSIB . EE has been directed to immediately take up repair work as a interim measures till regular tender for major repair/ renovation is taken up. O&amp;M agency has been directed to improve the cleanliness in the complex.</p>															

### Inspection Report of visit to Toilet Complexes in AC-17 Wazirpur Area on 14.02.2018

An inspection of toilet complexes of DUSIB was carried out by Chief Engineer (Coordn.), DUSIB alongwith Ms. Sarika Chaudhary, Member DCW and other officers of DUSIB.

S.No	Div.	AC. No	Code of JSC	Location	No of Seats	Type of Building	SL/ST	O & M agency	Water	Lighting	Cleanliness	Disp Board	Drainage	O&M	Fixtures
6	C04	17	17CJ0409	B-Block, Shamshan ghat Wazirpur JJ Colony	20	Pucca	SL	M/s H K Professional Pvt Ltd	Available	available	satisfactory	available	available	available	available
<p>Observations : The complex was found in good condition</p> <p style="text-align: center;">Action : EE has been directed to maintained the complex as such.</p>															
7	C04	17	17CJ0408	In front of E&F-Billock, Patharwala Bagh, Wazirpur Ph-IV	40	Pucca	SL	M/s. Mahatama Jyoti scavangin g Mukti Sansthan	Available	available	satisfactory	available	available	available	available
<p>Observations : It was alleged by 02 users that Rs 2 is being charged by the caretaker but other more users say that for the last more than one month, no money is being charged. This is a 30 years contract complex . The complex was to be taken up for renovation.</p> <p style="text-align: center;">Action : The work of upgradation is under award and upgradation work will be taken up by 15-03-2018 and hope to complete the work by September, 2018</p>															
8	C04	17	17CJ0499	J3 Block Wazirpur JJ Colony(JSC-2)	51	Pucca	SL	M/s H K Professional Pvt Ltd	Available	available	satisfactory	available	available	available	available
<p>Observations : Member DCW raised the issue of unsatisfactory cleanliness in the complex and found broken door shutter</p> <p style="text-align: center;">Action : The complex was recently taken over from North MCD and repair work could not be taken up due to non availability of funds under Revenue Head. EE has been directed to immediately take up repair work as an interim measures till regular arrangement for major repair/ renovation is taken up. O&amp;M agency has been directed to improve the cleanliness in the complex.</p>															

### Inspection Report of visit to Toilet Complexes in AC-17 Wazirpur Area on 14.02.2018

An inspection of toilet complexes of DUSIB was carried out by Chief Engineer (Coordn.), DUSIB alongwith Ms. Sarika Chaudhary, Member DCW and other officers of DUSIB.

S.No	Div.	AC. No	Code of JSC	Location	No of Seats	Type of Building	SL/ST	O & M agency	Water	Lighting	Cleanliness	Disp Board	Drainage	O&M	Fixtures

P.S.: The videography of the inspection carried out of the toilet complexes as mentioned above has been done and the record is available in DUSIB office.

## Delhi Urban Shelter Improvement Board Inspection Report of visit to Toilet Complexes in AC-41, Jangpura and AC-51, Kalkaji on 15.02.2018

An inspection of toilet complexes of DUSIB has been carried out by Ms. Sarika Chaudhary, Member DCW along with CE-I, DUSIB and other officers of DUSIB.

S.No	Div.	AC. No	Code of JSC	Location	No of Seats	Type of Building	SL/ST	O & M agency	Water	Lighting	Cleanliness	Disp Board	Drainage	O&M	Fixtures
	C 05	41	41CJ0611	Pratap Camp behind Gurudwara Nehru Nagar	21	Pucca	SL	VIMHANS (Under CSR)	Available	available	satisfactory	available	available	available	available
1.	<p>Observations : The Member DCW desired to improve the cleanliness. Few cisterns in WCs were not functioning properly in gents section. The lights in some of the WCs were not functional. The complex is open round the clock.</p> <p style="text-align: center;">Action : The complex is overall satisfactory. The O&amp;M agency has been directed to improve the cleanliness in the complex. The Area EE (Civil), DUSIB has been directed to attend the deficiency in the cisterns in all the WCs. The concerned EE (Elect.) has also been directed to check all the lights in the complex today itself and to ensure that all the lights are functional.</p>														
	C05	41	41CJ0657	JJC Adivasi Camp behind PGDAV College Nehru Nagar	41	Pucca	ST	M/s Delhi Paryavara n Vikas Samiti	Available	available	satisfactory	available	available	available	available
2	<p>Observations : The complex was overall satisfactory. One number WC was locked due to chokage and one number WC was not clean in ladies section. The complex remains open round the clock. The JJ Dwellers reported that the care taker is changed frequently.</p> <p style="text-align: center;">Action : The concerned EE (Civil) has been directed to take the action to make the chocked WCs functional immediately. The O&amp;M agency informed that the care taker is having some family issues and therefore he has to visit his hometown frequently however, it has been assured by the O&amp;M agency that the alternative caretaker is available.</p>														
	C05	41	41CJ0612	Indira Camp MCD School, Block 10, Nehru Nagar	19	Pucca	SL	M/s Delhi Paryavara n Vikas Samiti	Available	available	satisfactory	available	available	available	available
3	<p>Observations : The complex was overall satisfactory. The complex is not open during late night hours. The Member, DCW suggested that Mahila Helpline Number - 181 be also displayed in all the Jan Suvidha Complexes maintained by DUSIB.</p> <p style="text-align: center;">Action : The nearby women JJ Dwellers informed that they have forced the care taker to close the complex during late night hours due to law and order issue and to open on call by the user only. The suggestion to display the Mahila Helpline Number - 181 has been noted for implementation.</p>														

## Inspection Report of visit to Toilet Complexes in AC-41, Jangpura and AC-51, Kalkaji on 15.02.2018

An inspection of toilet complexes of DUSIB has been carried out by Ms. Sarika Chaudhary, Member DCW along with CE-I, DUSIB and other officers of DUSIB.

S.N	Div.	AC. No	Code of JSC	Location	No of Seats	Type of Building	SL/ST	O & M agency	Water	Lighting	Cleanline ss	Disp Board	Drainage	O&M	Fixtures
	C06	51	51CJ0825	Karpuri Thakur Jan Jeewan Camp, Srinivaspuri ID-2167	24	Pucca	ST	M/s HK Profession al Pvt. Ltd.	Available	available	satisfact ory	available	available	available	available
4	<p>Observations : 3 no. WCs were reported chocked in ladies section. The Member, DCW desired to improve the cleanliness in the complex. She also suggested that the 2nd gate in the boundary wall be also locked from the inside to avoid any illegal entry to the women section.</p> <p style="text-align: center;">Action : The area EE has been directed to take immediate action to make the chocked WC functional. The gate in the boundary wall shall be locked today itself. The care taker of O&amp;M agency was directed to sensitize the women users not to dispose the sanitary napkins in WCs to avoid chockage and the sanitary napkins be disposed in dustbin only kept in the ladies section for the purpose.</p>														
	C05	41	41CJ0614	Jal Vihar Railway Line Shiv Mandir Marg Lajpat Nagar	38	Pucca	SL	M/s Delhi Paryavara n Vikas Samiti	Available	available	satisfact ory	available	available	available	available
5	<p>Observations : The complex was found clean during the visit. 2 no. taps were missing in ladies section. No sweeper was available at the time of inspection. Complex is not open during late night hours.</p> <p style="text-align: center;">Action : The O&amp;M agency assured that missing taps shall be provided today itself. The O&amp;M agency also assured that the regular sweeper shall be deployed at this site. The JJ Dwellers did not favour the opening of complex during late night hours due to law and order issue and therefore complex is closed around 11:30 PM and opened only on the call of the user, if required.</p>														
	C05	41	41PJ0664	Madrasi Basti near Railway Line Jal Vihar	44	Prefab	ST	M/s Delhi Paryavara n Vikas Samiti	Available	available	satisfact ory	available	available	available	available
6	<p>Observations : The complex was overall satisfactory. The nearby resident complained regarding accumulation of filthy water outside the boundary of the complex and near his residence.</p> <p style="text-align: center;">Action : The area EE informed that the work of laying the pipeline for disposal of overflow of septic tank to the nearby sewer line is in progress and shall be completed within 2-3 days.</p>														

## Inspection Report of visit to Toilet Complexes in AC-41, Jangpura and AC-51, Kalkaji on 15.02.2018

An inspection of toilet complexes of DUSIB has been carried out by Ms. Sarika Chaudhary, Member DCW along with CE-I, DUSIB and other officers of DUSIB.

S.No	Div.	AC. No	Code of JSC	Location	No of Seats	Type of Building	SL/ST	O & M agency	Water	Lighting	Cleanliness	Disp Board	Drainage	O&M	Fixtures
7	C05	41	41PJ0661	Madras Basti near Railway Line Jai Vihar	110	Prefab	ST	M/s Delhi Paryavara n Vikas Samiti	Available	available	satisfactory	available	available	available	available
<p>Observations : The complex was found overall satisfactory. The Member, DCW observed that the cleaning in WCs in ladies section is not proper. The supervisor of O&amp;M Agency informed that most of the user did not flush the WC after use and sweeper cleans WC as and when noticed by him</p> <p style="text-align: right;">Action : The O&amp;M Agency has been directed to improve the cleanliness. The O&amp;M agency has also been directed to sensitize the users regarding flushing of WCs after use.</p>															

P.S. : The videography of the inspection carried out of the toilet complexes as mentioned above has been done and the record is available in DUSIB Office.

DelhiUrban Shelter Improvement Board  
Inspection Report of visit to Toilet Complexes in AC-04 Adarsh Nagar Area on 16.02.2018

An inspection of toilet complexes of DUSIB was carried out by CEO, DUSIB alongwith Smt.Promila Gupta, Member DCW and other officers of DUSIB.

S. No	Div. AC. No	Code of JSC	Location	No of Seats	Type of Building	SL/ST	O & M agency	Water	Lighting	Cleanliness	Disp Board	Drainage	O&M	Fixtures
	C11 04	4C11404	JJ Basti Sarai, Pipal thala, Adarsh nagar, Site No.1	31	Pucca	SL	Delhi Paryavaran vikas samiti	Available	available	satisfactory	available	available	available	available
<p>Observations : The complex was overall satisfactory. The large number of users were found at the time of inspection and the complex was almost over crowded being peak hours. The JJ Dwellers and the care taker informed that around 2000 persons are using this toilet block daily. The complex remains open round the clock. Member(DCW) suggested to cater additional demand of toilet, 2nos. bathroom in ladies section be converted to WC's and for better illumination additional LEDs in this toilet block be also installed. Apart from this she has also suggested to take extra care to maintain cleanliness of the complex during peak hours.</p> <p>Action : EE C-11, EE E-4 have been directed to take immediate action for the conversion of 2 nos. bathroom to WC's and to provide extra lighting arrangements (LEDs) respectively. The O&amp;M agency has also been asked to maintain more cleanliness during peak hours.</p>														
	C11 04	4C11403	JJ Basti Sarai, Pipal thala, Adarsh nagar, Site No.2	27	Pucca	SL	Delhi Paryavaran vikas samiti	Available	available	satisfactory	available	available	available	available
<p>Observations : The complex was overall satisfactory. The large number of users were found at the time of inspection and the complex was almost over crowded being peak hours.. The complex remains open round the clock. Member(DCW) suggested to cater additional demand of toilet, 2nos. bathroom in ladies section be converted to WC's and for better illumination additional LEDs in this toilet block be also installed. Apart from this she has also suggested to take extra care to maintain cleanliness of the complex during peak hours.</p> <p>Action : EE C-11, EE E-4 have been directed to take immediate action for the conversion of 2 nos. bathroom to WC's and to provide extra lighting arrangements respectively.</p> <p>The O&amp;M agency has also been asked to maintain more cleanliness during peak hours..</p>														

3

C11	04	4CJ1402	JJ Basti H-2 block double storey, Jahangir puri	40	Pucca	SL	Rajya Jan vikas samiti	Available	available	satisfactory	available	available	available
<p>Observations : The complex was overall satisfactory. Member (DCW) suggested for better illumination additional LEDs in this toilet block be installed. Users of the complex complained for non availability of adequate soap/cleaning material.</p> <p>Action : EE E-4 have been directed to take immediate action to provide extra lighting arrangements (LEDs)in toilet complex. The O&amp;M agency has also been asked to provide sufficient soap/cleaning material on daily basis.</p>													
C11	04	4CJ1401	JJ Basti G block Jahangir puri	20	Pucca.	SL	M/s.Sindh u social Welfare & Environme nt society	Available	available	satisfactory	available	available	available
<p>Observations : The complex was overall satisfactory.</p> <p>Action : EE C-11and O&amp;M agency directed to upkeep the complex clean and functional</p>													

P.S.: The videography of the inspection carried out of the toilet complexes as mentioned above has been done and the record is available in DUSIB office.



①

## Inspection Report of visit to Toilet Complexes in AC-49, Sangam Vihar and AC-52, Tughlakabad on 17.02.2018

An inspection of toilet complexes of DUSIB has been carried out by Smt. Farheen Mallick, DCW along with Member (Engg.), CE-I and other officers of DUSIB.

S. No	Div.	AC. No	Code of JSC	Location	No of Seats	Type of Building	SL/ST	O & M agency	Water	Lighting	Cleanline ss.	Disp Board	Drainage	O&M	Fixtures
4	C06	52	52CJ0905	Sanjay Colony Y-Block at No. Y-5 to Y-8 and back lane of Y-1 to Y-12 and ESS Okhla Ind. Area Phase-II (Site -2)	108	Pucca	SL	M/s Jyoti Samajik Sewa Sansthan	Available	available	satisfactory	available	available	available	available
<p>Observations : The toilet complex was found clean and in good condition.                      EE (Civil) is directed to maintain the complex in such condition in future also.</p> <p style="text-align: right;">Action : The concerned</p>															
5	C06	52	52CJ0904	Sanjay Colony Y-Block at No. Y-5 to Y-8 and back lane of Y-1 to Y-12 and ESS Okhla Ind. Area Phase-II (Site -1)	108	Pucca	SL	M/s Jyoti Samajik Sewa Sansthan	Available	available	satisfactory	available	available	available	available
<p>Observations : The toilet complex was found clean and in good condition.                      (Civil) is directed to maintain the complex in such condition in future also.</p> <p style="text-align: right;">Action : The concerned EE</p>															

P.S. : The videography of the inspection carried out of the toilet complexes as mentioned above has been done and the record is available in DUSIB Office.