

GOVT. OF NCT OF DELHI
PWD SECRETARIAT: 5TH LEVEL: B-WING
DELHI SECTT. : I.P.ESTATE: NEW DELHI

F. No.11(163)/2017/PWD-II/VS | 11597
CD No. 057447589

Dated: 9/8/2017

To,

Dy. Secretary,
Delhi Legislative Assembly,
Question Branch, Old Sectt.,
Delhi-110054.

**Sub.: Legislative Assembly Starred Que. No.50 Raised by Hon'ble MLA,
Sh. S. K. Bagga for 10.8.2017.**

Sir,

Kindly refer to Dy. Secretary (Q), Legislative Assembly Secretariat (Question Branch) letter No. F-11(B-I)VI/2015-19/DVS/Que. Branch/ dated 31.7.2017 on the subject cited above. In this regard please find enclosed 100 copies of Reply of Vidhan Sabha Question mentioned for necessary action at your end please. However, the copy of the same also sent through e.mail.

Yours faithfully,

Encl: As above


(DEBASIS BISWAL)
DY. SECRETARY (PWD/VS)

विभाग का नाम :- लोक निर्माण विभाग, दिल्ली सरकार
 विभाग का पता :- 5वाँ तल, बी-विंग, दिल्ली सचिवालय, इन्द्रप्रस्थ संपदा,
 नई दिल्ली-110002.

तारांकित प्रश्न संख्या :-50

दिनांक :-10/08/2017

प्रश्नकर्ता का नाम :- श्री एस. के. बग्गा

क्या लोक निर्माण विभाग मंत्री यह बताने की कृपा करेंगे कि :-

क स	प्रश्न	उत्तर
(क)	कृष्णा नगर विधान सभा क्षेत्र में पी0.डब्लू0.डी0. के नालों की सफाई कब हुई थी,	सफाई का ब्यौरा सलंगन है। फ्लोटिंग मैटीरियल निकालने का कार्य अभी भी चल रहा है।
(ख)	संबंधित ठेकेदार का ब्यौरा व उसे भुगतान की गई धनराशि।	मैसर्स साईं ट्यूब वेल एवं भुगतान की गई राशि रु 2.00 लाख (लगभग) एवं मैसर्स टी0.के0.एन0.डवलपर्स को अभी तक कोई भुगतान नहीं किया गया है।
(ग)	कृष्णा नगर विधान सभा क्षेत्र में लोक निर्माण विभाग की सडकों का ब्यौरा,	रोड न0. 57, जगतपुरी से बिहारी कालोनी तक, एवं डियूस्ड कैनाल से झील चौक तक।
(घ)	ताज एन्कलेव-रानी गार्डन पर, जहा उपरिगामी सेतु न होने से अनेक लोगों की मृत्यु हो चुकी है, बनने वाले उपरिगामी सेतु के निर्माण की स्थिति, और	उपरिगामी सेतु का प्रस्ताव एफ0ओ0बी0/सबवे कमेटी के द्वारा जनवरी 2017 में सम्भव (फीजीबल) नहीं पाया गया।
(ङ)	कृष्णा नगर विधान सभा क्षेत्र में पदस्थ लोक निर्माण विभाग के विभिन्न के विभिन्न अधिकारियों की जिम्मेदारिया तथा उनका संपर्क-ब्यौरा	उपरोक्त (ग) के अनुसार रोड के कुछ भाग के लिये : 1. श्री विजय सिंह, कार्यपालक अभियन्ता (सिविल)सम्पर्क-ब्यौरा 8802028700 2. श्री वी0.के0.गोयल, सहायक अभियन्ता सम्पर्क-ब्यौरा 9873760538 3. श्री ए0.के0.सिंह, कनिष्ठ अभियन्ता सम्पर्क-ब्यौरा 9810255098 4. श्री इकबाल सिंह, कार्यपालक अभियन्ता (011-22452056) 5. श्री राकेश कुमार शर्मा, सहायक अभियन्ता (9958998336) 6. श्री संजय कुमार राव, कनिष्ठ अभियन्ता (8447023542)

उपरोक्त उत्तर माननीय मंत्री, लोक निर्माण विभाग की स्वीकृति से जारी किया गया है।

(देवासीस बिसवाल)
 उप सचिव (लो0नि0वि0)
 दूरभाष: 23392296

PWD Desilting Report (Preparedness for Monsoon)

DESILTING REPORT UNDER PWD MAINTENANCE EAST ZONE									
As on 04.08.2017									
Sl. No.	Name of Road / Drain	Length of Road (Km)	Contractor	Date of Start of De-silting	Date of completion (1st Cycle)	% Drain cleaned (Lengthwise)	Estimate Qty. of silt (cum)	Qty. of silt lifted and disposed off (cum)	EE in charge / Mobile No.
1	2	3	4	5	6	7	8	9	10
Circle/ Divn. :- Shahadara/ Shahdara (Road) Div.									
Name of MLA : Sh. S.K. Bagga									
Name of Constituency :- Krishna Nagar									
1	Road No. 57 (Karkari More to Azad Nagar)	2.52	M/s T.K.N. Developers	25.02.2017	20.07.2017	100%	1920	1920	Sh Vijay Singh 8802028700
Circle/ Divn. :- East (Road)									
Name of MLA : Sh. S.K. Bagga									
Name of Constituency :- Krishna Nagar									
1	Disused canal road (Main Drain with EDMC)	2.90	M/s Sai Tube Well	15.03.2017	14.08.2017	75%	870		Sh. Iqbal Singh 9910925748
2	Patparganj Road (50% of total length from Disues canal road to Jheel)	2.89		15.03.2017	14.08.2017	75%	2691.67		


 Executive Engineer (P)
 (East) M, PWD