

दिल्ली शहरी आश्रय सुधार बोर्ड

दिल्ली सरकार

क्रमांक: एफ-7/पी.सी./ए.क्यू.सी.64/डी-48


दिनांक: 20/03/18

विषय:—श्री सही राम, विधायक द्वारा पूछे गये विधान सभा अतांकित प्रश्न संख्या 64 दिनांक 20/03/2018 का उत्तर।

प्रश्न	उत्तर
(क) डीयूएसआईबी की इलेक्ट्रिकल तथा सिविल विंग की विभिन्न डिवीजनों के निरीक्षण से संबंधित क्वालिटी कंट्रोल के कितने पैरा लंबित हैं,	जुलाई 2010 में डुसिब के गठन के उपरान्त, सिविल तथा इलेक्ट्रिकल विंग के विभिन्न कार्यों के निरीक्षण से संबंधित क्वालिटी कंट्रोल के 254 पैरा लंबित है।
(ख) पिछले दस वर्षों की अवधि के लिए इनका वर्षवार ब्यौरा उपलब्ध कराएं,	2010 से 2018 तक कि अवधि के लिए वर्ष वार ब्यौरा संलग्न तालिका -1 में दिया हुआ है
(ग) कितने ठेकेदारों को डीयूएसआईबी में काम की खराब गुणवत्ता के लिए क्वालिटी कंट्रोल के अध्यक्ष द्वारा काली सूची में डालने के लिए संस्तुत किया गया है,	क्वालिटी कंट्रोल शाखा द्वारा किसी भी ठेकेदार को काली सूची में डालने के लिए संस्तुत नहीं किया गया है।
(घ) काम की खराब गुणवत्ता के लिए कार्यरत स्टाफ क् विरुद्ध क्वालिटी कंट्रोल के अध्यक्ष द्वारा कुल कितनी संस्तुतियां की गईं,	विगत वर्षों में काम की खराब गुणवत्ता के लिए चार केसों में कार्यरत स्टाफ के विरुद्ध सतर्कता विभाग को कार्यवाही हेतु संस्तुतियां की गईं
(ङ) डीयूएसआईबी के चल रहे कार्यों/परियोजना के लिए क्या कोई निगरानी तंत्र है,	विभिन्न कार्य परियोजनाओं के लिए संबद्धित अधिशासी अभियन्ता के कार्यालय द्वारा नियमित निगरानी की जाती है। इस के अलावा क्वालिटी कंट्रोल शाखा द्वारा 25 लाख लागत तक के कार्य रैन्डम बेसिस पर चेक किये जाते हैं तथा 25 लाख से 100 लाख लागत तक के कार्य अनिवार्य रूप से चेक किये जाते हैं। 100 लाख से ज्यादा लागत के कार्य अनिवार्य रूप से थर्ड पार्टी से चेक कराए जाते हैं।
(च) यदि हां, तो उसका पूरा विवरण दें,	उपरोक्त तंत्र में कनिष्ठ अभियन्ता, सहायक अभियन्ता एवम अधिशासी अभियन्ता के द्वारा विभिन्न कार्यों का अवलोकन किया जाता है। समय समय पर किसी भी कार्य परियोजना का निरीक्षण उच्च अधिकारियों जैसे अधीक्षण अभियन्ता, मुख्य अभियन्ता एवम मैम्बर (ई.) द्वारा भी किया जाता है।

(छ) डीयूएसआईबी के निगरानी तंत्र का उत्तरदायित्व किसका है,	संबंधित अधिशासी अभियंता के कार्यालय का उत्तरदायित्व होता है।
(ज) इस निगरानी के क्या परिणाम रहे हैं, डीयूएसआईबी परियोजनाओं की निगरानी के विगत दस वर्षों के परिणाम का विवरण क्या है,	कार्यों में कमी पाये जाने पर संबंधित अधिशासी अभियंता के कार्यालय द्वारा कार्य को दुरुस्त करना सुनिश्चित किया जाता है। इसीब के गठन के उपरान्त क्वालीटी कंट्रोल शाखा द्वारा 1072 कार्यों का निरीक्षण किया गया जिन में पायी गई कमीयों को ठीक करने के उपरान्त 818 कार्यों के पैरा ड्रॉप कर दिए गए हैं तथा 254 कार्यों के पैरा अभी लंबित हैं।
(झ) डीयूएसआईबी के शौचालय परिसरों के परिचालन/ रखरखाव के लिए क्या कोई निगरानी तंत्र है, और	संबंधित अधिशासी अभियंता की देख रेख में शौचालय परिसरों के परिचालन/रखरखाव का कार्य किया जाता है तथा अभी एस. बी. एम. शाखा द्वारा भी यह कार्य किया जा रहा है
(ट) विगत पांच वर्षों की निगरानी रिपोर्ट तथा फील्ड स्टाफ द्वारा की गई कार्रवाई का विवरण क्या है?	संबंधित अधिशासी अभियंता व सहायक अभियंता नियमित निगरानी करते हैं, परन्तु उसकी कोई रिपोर्ट नहीं बनाते एवं उसी स्थान पर कमियों को दूर करने के लिए निर्देश जारी कर देते हैं। डीयूएसआईबी ने अलग से पांच टीमों अधिशासी अभियंताओं के अन्तर्गत लगाई गई हैं। ईई (एस. बी. एम.) की टीम 29.11.2017 से लगायी हैं व उनकी सेम्पल रिपोर्ट संलग्न है। इसके अलावा पिछले दो वर्षों से कुछ टीमों में मॅम्बर एक्सपर्ट के अन्तर्गत अलग से निगरानी करती थी व रिपोर्ट मॅल के द्वारा सभी को भेजी जाती थी। इसका ब्योरा 26.03.2018 तक उपलब्ध कराने का पूर्ण प्रयास रहेगा।

यह उत्तर सक्षम अधिकारी की पूर्व अनुमति से प्रेषित किया जाता है।


उप निदेशक (संसद प्रकोष्ठ)

उप सचिव (प्रश्न शाखा), पुराना सचिवालय, दिल्ली सरकार

Annex I

लंबित क्यू सी पैरो का वर्षवार ब्यौरा (पशन संख्या 64 ख के अर्थभा में)

तालिका - 1

क्रमांक	वर्ष	लंबित पैरो की संख्या
1.	2010-11	12
2.	2011-12	04
3.	2012-13	13
4.	2013-14	12
5.	2014-15	07
6.	2015-16	37
7.	2016-17	44
8.	2017-18	125
	कुल योग	254

SE (A/C)

EE (A/C)

DELHI URBAN SHELTER IMPROVEMENT BOARD

Punarwas Bhawan, IP Estate, New Delhi - 110002

DAILY JSC INSPECTION REPORT

Status: **Deficient**, For area: **All**

Status as on: **04 January, 2018 till 05:57:10 pm**

Total Number of JSCs: 620; Total Seats: 18713; Total Reports Received: 619;
Area of Jurisdiction (All)

Note:

1. In case for Functional status of JSCs "F" represents Functional and "N" Non Functional.
2. In the status report of all other conditions "A" represent "Satisfactory" and "B" represents "Deficient".
3. Blank cell denote report is not submitted for that particular item.
4. The reporting system is currently open till midnight of every day. Due to this the report generated in any time of the day may vary in case of further reporting is continue.

JSC Status Summary Report for 04 January, 2018*

Status	Good	Bad	No Report	Total
Functional	613	6	1	620
Water	605	13	2	620
Lighting	610	8	2	620
Cleanliness	595	23	2	620
Disp Board	615	3	2	620
Drainage	608	10	2	620
O&M	595	23	2	620
Over All	595	24	1	620

Division-wise JSC Report Details for 04 January, 2018*

Division	Good	Bad	No Report	Total	Ex.Eng.
SBM01	48	7	0	55	Sh. Naresh Gera (9717999343)
SBM02	123	5	1	129	Sh. P.D. Ashok (9650298800)
SBM03	149	4	0	153	Sh. Phool Singh (9717999275)
SBM04	132	14	0	146	Sh. K.B Sharma (9717999325)
SBM05	135	2	0	137	Sh. Pardeep Kr. Garg (9717999271)
Total	587	32	1	620	

Daily Inspection Report of JSCs

List of JSCs which have not been reported on 04 January, 2018 till 05:57:10 pm

S.No.	JSC Code and Name	Division	Ex.Eng.	Agency
1	Sanjay Colony Mehrauli -Bhatti Mines at community hall ID: 46RJ0915	SBM02	Sh. P.D. Ashok (9650298800)	YLDA India Pvt Ltd

List of Deficient JSCs reported on 04 January, 2018 till 05:57:10 pm for area All

S.No.	Details of JSC	Functional	Water	Lighting	Cleanliness	Disp Board	Drainage	O&M	Over All	Comment
1	Back of Commercial Centre, Mayapuri ID: 28CJ0002 Div: SBM01 Seats: 8 Ag: Socail Skill Vision Society EE: Sh. Naresh Gera (9717999343)	F	B	A	B	A	A	B	B	Complex is under repair and cleaning found unsatisfactory, No Photo By: 9717999229, at: 04:13 pm
2	WZE Block Mata Mandir Road Maya Puri. ID: 28CJ0004 Div: SBM01 Seats: 43 Ag: Akhil Bhartiya Prayavaran Gramin Vikas Sansthan. EE: Sh. Naresh Gera (9717999343)	F	A	A	B	A	A	B	B	Not found satisfactory, No Photo By: 9717999229, at: 04:17 pm
3	WZE Block Kanchan Basti Rewari Railway Line Maya Puri ID: 28CJ0005 Div: SBM01 Seats: 41 Ag: Akhil Bhartiya Prayavaran Gramin Vikas Sansthan. EE: Sh. Naresh Gera (9717999343)	F	A	A	B	A	A	B	B	Cleaning not found satisfactory., No Photo By: 9717999229, at: 04:08 pm
4	C187 Maya Puri Phase.II. ID: 28MJ0008 Div: SBM01 Seats: 14 Ag: Socail Skill Vision Society EE: Sh. Naresh Gera (9717999343)	F	A	A	B	A	A	A	B	The existing MTV is in a very bad condition and need to replace at earliest., Photo: 1 By: 9717999229, at: 03:57 pm

Daily Inspection Report of JSCs

S.No.	Details of JSC	Functional	Water	Lighting	Cleanliness	Disp Board	Drainage	O&M	Over All	Comment
5	Shanker Garden B Block Vikas Puri, Site-1 ID: 29CJ0017 Div: SBM01 Seats: 31 Ag: Divya Pollution control and Social Organisation EE: Sh. Naresh Gera (9717999343)	F	B	A	B	A	A	B	B	The roof tank was found under repair. So there was less water availability., No Photo By: 9717999229, at: 03:43 pm
6	Gali No.7 Mahavir Enclave ID: 33CJ0021 Div: SBM01 Seats: 20 Ag: South-West Delhi Educational and Cultural Society EE: Sh. Naresh Gera (9717999343)	F	A	A	B	A	A	B	B	The overall condition is very poor as the JSC is reported under construction. The JSC is running through unauthorized electric meter and today raided by enforcement of electricity deptt.of Delhi as reported by the Pradhan., Photo: 6 By: 9717999229, at: 03:18 pm
7	Back of Commercial Centre, Mayapuri, Site-2 ID: 28PJ0034 Div: SBM01 Seats: 30 Ag: Delhi Paryavaran Vikas Samiti EE: Sh. Naresh Gera (9717999343)	F	B	A	B	A	A	B	B	**Running through unauthorized electric meter connection.**, No Photo By: 9717999229, at: 04:11 pm
8	Amar Park Infront of HIL Factory Gate, Petrol Pump, Zhakira ID: 25PJ0508 Div: SBM02 Seats: 32 Ag: International Social Service Centre EE: Sh. P.D. Ashok (9650298800)	F	B	A	A	A	A	A	A	Upgradation Required Work allotted to HPCL for Renovation Boring in progress , No Photo By: 9634858580, at: 04:13 pm

Daily Inspection Report of JSCs

S.No.	Details of JSC	Functional	Water	Lighting	Cleanliness	Disp Board	Drainage	O&M	Over All	Comment
9	Old Cloth Market Raghubir Nagar ID: 27CJ0510 Div: SBM02 Seats: 20 Ag: Social care reforms Socity EE: Sh. P.D. Ashok (9650298800)	N							B	The JSC needs extensive repair. The O&M agency contract was terminated. Repair estimate was framed and is in process., No Photo By: 9780184890, at: 03:16 pm
10	IG Camp No. 1 near Sidharth Basti near Hari Nagar Ashram ID: 41CJ0659 Div: SBM03 Seats: 21 Ag: M/s Delhi Paryavaran Vikas Samiti. EE: Sh. Phool Singh (9717999275)	F	B	B	B	A	A	B	B	No Electric connection available, No Photo By: 9717999264, at: 04:38 pm
11	Madrasi Basti Near Railway Line Jal Vihar ID: 41PJ0664 Div: SBM03 Seats: 44 Ag: Delhi Paryavaran Vikas Samiti EE: Sh. Phool Singh (9717999275)	N	A	A	B	A	A	B	B	Locked during inspection, No Photo By: 9717999264, at: 04:33 pm
12	Janta Jeewan Camp Tigri Part-II (H-Block) ID-1964 ID: 47CJ0808 Div: SBM03 Seats: 41 Ag: Azad Samajik Sewa Sanstha EE: Sh. Phool Singh (9717999275)	N	A	A	B	A	A	B	A	J.s.c. is closed due to construction of Nallah by SDMC, No Photo By: 9717999275, at: 01:08 pm
13	Bilas Pur Camp Molar Bandh NTPC ID: 53CJ0881 Div: SBM03 Seats: 63 Ag: Manav Sewa Kalyan Samiti EE: Sh. Phool Singh (9717999275)	F	A	A	B	A	A	B	B	E.E. May kindly be requested to see it in person and made another arrangement of toilet , No Photo By: 9717999275, at: 03:38 pm

Daily Inspection Report of JSCs

S.No.	Details of JSC	Functional	Water	Lighting	Cleanliness	Disp Board	Drainage	O&M	Over All	Comment
14	Nand Lal Camp Near Gopalpur Village (Part-I) ID: 3CJ1008 Div: SBM04 Seats: 6 Ag: RWA EE: Sh. K.B Sharma (9717999325)	F	B	B	B	A	B	B	B	2 wc broken, No Photo By: 8130596144, at: 03:40 pm
15	east of 64 khamba ID: 21CJ1080 Div: SBM04 Seats: 6 Ag: RWA EE: Sh. K.B Sharma (9717999325)	N	B	B	A	A	B	B	B	Closed due to renovation required Door damaged Electric connection not available, No Photo By: 8826397610, at: 02:58 pm
16	JJC Shakoor Ki Dandi (Basti Khawaja) ID: 21CJ1081 Div: SBM04 Seats: 4 Ag: RWA EE: Sh. K.B Sharma (9717999325)	F	B	A	B	A	B	B	B	No meter Street light illuminates to some extent, No Photo By: 9717999325, at: 04:20 pm
17	64 Khamba Dhobi Ghat No.26, J.N.Marg ID: 21CJ1083 Div: SBM04 Seats: 5 Ag: RWA EE: Sh. K.B Sharma (9717999325)	N	B	B	B	B	B	B	B	Local residents Door damaged Floor required repair No electric connection Required renovation, No Photo By: 8826397610, at: 03:00 pm
18	Pushta Between Old Seemapuri, DLF Dilshad Garden (Indira Nehru Camp Part II) ID: 62CJ1103 Div: SBM04 Seats: 32 Ag: Arya Bhatt Sewa Sansthan EE: Sh. K.B Sharma (9717999325)	F	A	A	B	A	B	B	B	4 wc 7 doors broken , No Photo By: 9717999180, at: 12:57 pm

Daily Inspection Report of JSCs

S.No.	Details of JSC	Functional	Water	Lighting	Cleanliness	Disp Board	Drainage	O&M	Over All	Comment
19	H Block Kalender Colony, Dilshad Garden Part II ID: 62CJ1110 Div: SBM04 Seats: 44 Ag: Manav Sewa Kalyan Samiti EE: Sh. K.B Sharma (9717999325)	F	A	A	B	A	B	B	B	16 doors broken , No Photo By: 9717999180, at: 04:04 pm
20	Block D 1&2 Nand Nagari (I) ID: 63CJ1122 Div: SBM04 Seats: 40 Ag: RWA EE: Sh. K.B Sharma (9717999325)	F	A	A	B	A	B	B	B	No electric meter, alternate arrangements done , No Photo By: 9717999180, at: 04:49 pm
21	Block D 1&2 Nand Nagari (II) ID: 63CJ1126 Div: SBM04 Seats: 40 Ag: RWA EE: Sh. K.B Sharma (9717999325)	F	A	A	B	A	B	B	B	No electric meter, alternate arrangements done , No Photo By: 9717999180, at: 01:41 pm
22	F1 F2 Sunder Nagari ID: 63CJ1127 Div: SBM04 Seats: 84 Ag: RWA EE: Sh. K.B Sharma (9717999325)	F	A	A	B	A	B	B	B	38 wc chocked , No Photo By: 9717999180, at: 01:44 pm
23	MCD Land Friends colony Gate No.1 ID: 62MJ1138 Div: SBM04 Seats: 14 Ag: RWA EE: Sh. K.B Sharma (9717999325)	F	B	B	A	A	A	B	B	Unsatisfactory , No Photo By: 9717999180, at: 04:15 pm
24	Chander Puri Railway Lines Old Seelam Pur ID: 61CJ1147 Div: SBM04 Seats: 42 Ag: RWA EE: Sh. K.B Sharma (9717999325)	F	A	A	A	B	A	A	A	Partly functioning , renovation work in progress , hence no proper cleaning , No Photo By: 9717999180, at: 04:25 pm

Daily Inspection Report of JSCs

S.No.	Details of JSC	Functional	Water	Lighting	Cleanliness	Disp Board	Drainage	O&M	Over All	Comment
25	AGCR Shahdara ID: 59MJ1221 Div: SBM04 Seats: 10 Ag: RWA EE: Sh. K.B Sharma (9717999325)	F	B	B	B	A	A	B	B	No electric meter No care taker , Photo: 1 By: 9717999325, at: 03:19 pm
26	C-Block, Jaina Tower Preet Vihar ID: 59CJ1243 Div: SBM04 Seats: 9 Ag: RWA EE: Sh. K.B Sharma (9717999325)	F	B	B	A	A	A	B	B	Care taker not found and cleaning required, No Photo By: 9818593711, at: 04:46 pm
27	Harizan Samiti Near Dispensary Mangal Bazar Mandavali ID: 58MJ1249 Div: SBM04 Seats: 10 Ag: RWA EE: Sh. K.B Sharma (9717999325)	F	B	A	A	A	A	A	A	No electricity connection but street lights sufficient, water line leaking ,bib cock damaged & Plumbing work in progress , No Photo By: 8527393465, at: 05:00 pm
28	JJ Camp near Farishta Soap Factory, Old Rohtak Road ID: 19CJ1303 Div: SBM05 Seats: 20 Ag: Jyoti Samajik Sewa Sansthan EE: Sh. Pardeep Kr. Garg (9717999271)	N	A	A	B	B	A	B	B	Due to renovation work this complex not functional, No Photo By: 9717999305, at: 02:15 pm
29	Kalander Colony Part C near Bhalswa Dairy ID: 5CJ1408 Div: SBM05 Seats: 65 Ag: Manav Uthan Maha Samiti EE: Sh. Pardeep Kr. Garg (9717999271)	F	A	A	A	A	B	A	A	All performance good , Photo: 1 By: 9953045583, at: 11:58 am
30	JJ Cluster Hoti Camp Rangpuri Pahari ID: 36RJ0549 Div: SBM02 Seats: 20 Ag: YLDA India Pvt Ltd EE: Sh. P.D. Ashok (9650298800)	F	A	A	B	A	A	A	A	Satisfactory , No Photo By: 9717999186, at: 03:33 pm

Daily Inspection Report of JSCs

11 of 11

S.No.	Details of JSC	Functional	Water	Lighting	Cleanliness	Disp Board	Drainage	O&M	Over All	Comment
31	JJ Cluster Israel Camp Rangpuri Pahari ID: 36RJ0550 Div: SBM02 Seats: 20 Ag: YLDA India Pvt Ltd EE: Sh. P.D. Ashok (9650298800)	F	A	A	B	A	A	A	A	Satisfactory, No Photo By: 9717999186, at: 03:34 pm
32	Sanjay Colony Mehrauli -Bhatti Mines near dispencery ID: 46RJ0914 Div: SBM02 Seats: 50 Ag: YLDA India Pvt Ltd EE: Sh. P.D. Ashok (9650298800)	F	A	B	A	A	A	A	A	Satisfactory, No Photo By: 9717999186, at: 03:20 pm

◆ END OF THE REPORT ◆