

दिल्ली शहरी आश्रय सुधार बोर्ड
राष्ट्रीय राजधानी क्षेत्र दिल्ली सरकार


अतारांकित प्रश्न संख्या-113

श्री मनोज कुमार

दिनांक-27.02.2019

क्रमांक	प्रश्न	उत्तर			
क	कोंडली विधान सभा क्षेत्र में कूल कितने बस्ती विकास केंद्र (BVK) हैं;	उपलब्ध रिकॉर्ड के अनुसार कोंडली विधान सभा क्षेत्र में 4 बस्ती विकास केंद्र हैं।			
ख	जिन संस्थाओं को ये बी. वी. के. अलॉटमेंट किये गए हैं, नाम, पते सहित उनका विवरण ;	क्र सं	स्थान	आवंटित का पता	कार्य
		1	ब्लॉक 14 बस स्टैण्ड खिचड़ीपुर ग्राउंड फ्लोर	श्री वाई पी आनंद, एन जी ओ गोधूलि c/o भगत चंद्रा हॉस्पिटल RZ F -1, महावीर एन्क्लेव, पालम डाबरी रोड, दिल्ली -45	फ्री एजुकेशन एवं हेल्थ केयर to स्लम चिल्ड्रन एवं अदर फैसिलिटीज
		2	ब्लॉक 19-20 कल्याणपुरी	1.श्री विध्या भूषण, एन जी ओ प्रज्ञा दीप ,ई -86 शशि गार्डन मयूर विहार फेस -1 नई दिल्ली 91 2.सुश्री कुमारी सरस्वती एन जी ओ इंडियन सोशल वेलफेयर सोसाइटी, 16/151, कल्याणपुरी, दिल्ली - 91	कटिंग एवं टेलरिंग ब्यूटी कल्चर एवं क्रेच सोशल वेलफेयर एक्टिविटीज
		3	ब्लॉक-17-21, साइट-2 कल्याणपुरी फर्स्ट फ्लोर	प्रियदर्शिनी त्रिपाठी एन जी ओ अल्पना फ्लैट 329 ग्राउंड फ्लोर स्वयं सेवा, CGHS, झिलमिल कॉलोनी दिल्ली -95	सोशल वेलफेयर एक्टिविटीज
		4	ब्लॉक-17-21, साइट-1	श्री विजेन्द्र एन जी ओ भारतीय लोक	स्किल डेवलपमेंट

		कल्याणपुरी	सुरक्षा संस्थान, 21/179, कल्याणपुरी दिल्ली - 91	वोकेशनल ट्रेनिंग to अनएम्प्लोयमेंट युथ एजुकेशन
ग	कितने बस्ती विकास केंद्र अभी तक खाली हैं;	उपरोक्त बस्ती विकास केन्द्रों में भिन्न रूप से कुछ स्थान खाली हैं। 1. ब्लॉक 14 बस स्टैंड खिचड़ीपुर (ग्राउंड फ्लोर) 2. ब्लॉक 14 बस स्टैंड खिचड़ीपुर (फर्स्ट फ्लोर) 3. ब्लॉक-17-21, कल्याणपुरी (साइट-2) 4. ब्लॉक-19, कल्याणपुरी (ग्राउंड फ्लोर)		
घ	कितनी अप्लीकेशन लंबित हैं;	3 आवेदन पत्र लंबित है क्योंकि 17वीं बोर्ड की बैठक के मिनिट्स के अनुसार वस्ती विकास केन्द्र आवंटन को रोक दिया गया है		
ड	क्या कौंडली विधान सभा में कोई शिशु वाटिका व मनोरंजन केंद्र है।	कोण्डली विधान सभा क्षेत्र के जे. जे बस्ती में 5 शिशु वाटिके व एक मनोरंजन केंद्र (वरिष्ठ नागरिकों के लिए) ब्लॉक-3, खिचड़ीपुर में है।		
च	यदि हां, तो किस संस्था को दिया हुआ है ;	अभी यह केंद्र किसी संस्था को आंबटित नहीं हुआ है।		
छः	यदि नहीं, तो उसके क्या कारण हैं; और	यह मनोरंजन केंद्र विधायक निधि से बनाया गया है। माननीय विधायक की तरफ से इस बाबत कोई भी अनुशंशा लंबित नहीं है। सोशल वेलफेयर डिपार्टमेंट में पत्र भेजा गया है और जब तक टेक ओवर नहीं होता पब्लिक के सोशल फंक्शन के लिए आवंटित किया जायेगा।		
ज	कौंडली विधान सभा क्षेत्र में डीयूसईबी लंबित योजनाओं का विवरण क्या है ?	कोण्डली विधान सभा क्षेत्र में डूसिब द्वारा किये गये और चल रहे कार्यों का विवरण संलग्न है।		


 उप निदेशक (संसद कक्षा)

उप-सचिव, संसदीय शाखा

दिल्ली विधान सभा, पुराना सचिवालय, दिल्ली सरकार


List of Works Completed / In Progress in AC-56

(KONDLI - Assembly Constituency)

S.No	Temp Code New	AC No	Name of Work	Div	Scheme	Status of Work	Tendered Amt in Lacs	DOS/ Likely date of start	As on date progress (in %age) For ongoing works	Date of completion / Likely Date of Completion
1.	908	56	Upgradation/special repair of BVK(single storey) in JJ Basti at block-17-21, Kalyanpuri (site-II)	C09	BVK	Work in Progress	3.55	12-Sep-18	90%	28-Feb-19
2.	910	56	Renovation/up-gradation work of Community Hall at block-13-14, Kalyanpuri.	C09	BVK	Work in Progress	4.53	17.02.19	2%	30-Mar-19
3.	895	56	Raising and improvement of deteriorated lanes by pdg. CC pavement and drain in JJ Basti at block-17-21, Kalyanpuri.	C09	EIUS	Work in Progress	32.22	01-Feb-19	5%	30-Apr-19
4.	901	56	Raising of lanes by P/L CC pavement and SW drain in JJ Basti at block-1, Khichripur.	C09	EIUS	Work in Progress	1.75	16.02.19	2%	15-Apr-19
5.	986	56	Construction of boundary wall of vacant land(adjoining JSC) at near block-11 and 18, Kalyanpuri.	C09	GIA	Work in Progress	11.09	22-Oct-18	60%	30-Apr-19
6.	987	56	Construction of boundary wall with fencing, raising of floor and allied works in work shop at Gazipur..	C09	GIA	Work in Progress	23.75	10-Feb-19	5%	30-Mar-19
7.	988	56	Construction of boundary wall of vacant land of abandoned JSC at block-14, Kalyanpuri.	C09	GIA	Work in Progress	8.45	28-Dec-18	15%	30-Apr-19
8.	982	56	Construction of boundary wall of vacant land (near Gas Godown) at Block-1, Khichripur.	C09	GIA	Work in Progress	10.25	11.12.17	75%	30-Mar-19
9.	984	56	Construction of boundary wall of vacant land (Adjoining JSC) at near Block-11 and 18, Kalyanpuri.	C09	GIA	Work in Progress	11.09	17.02.19	60%	20-Mar-19
10.	972	56	A/R and M/O and providing APP Sheet at terrace with brick tiling, providing concertina coil fencing on parapet of JSC with some allied work in JSC 40 Seater in JJC at Block-11-12 Kalyanpuri.	C09	JSC	Work in Progress	2.27	19.02.19	10%	30-Mar-19
11.	975	56	A/R and M/O and development of tubewell bore at Night Shelter IFC Pocket-C, Gazipur.	C09	Night Shelter	Work in Progress	1.98	29-Jan-19	20%	20-Mar-19
12.	920	56	Construction of boundary wall and walk way of Shishu Vatika at block-17-21, Kalyanpuri.	C09	Shishu Vatika	Work in Progress	17.51	04-Feb-19	5%	15-Apr-19
13.	912	56	Construction of Basti Vikas Kendra (BVK) in JJ Basti (Adjoining NH-24) at Gazipur.	C09	BVK	Work Awarded	25.87	28-Feb-19	-NIL-	27-Jun-19

S.No	Temp Code New	AC No	Name of Work	Div	Scheme	Status of Work	Tendered Amt in Lacs	DOS/ Likely date of start	As on date progress (in %age) For ongoing works	Date of completion / Likely Date of Completion
14.	914	56	Engaging of Residential Care Taker for watch and ward of Community Hall building at IFC Pocket-C, Gazipur, Delhi.	C09	BVK	Work Awarded	2.63	28-Feb-19	-	27-Jan-20
15.	915	56	Re-boring of tubewell bore in BVK in JJ Basti at block-17-21, Kalyanpuri.	C09	BVK	Work Awarded	1.85	28-Feb-19	-	20-Mar-19
16.	916	56	Re-boring of tubewell bore in BVK in JJ Basti at block-17-21, Kalyanpuri (Site-1).	C09	BVK	Work Awarded	1.85	28-Feb-19	-	20-Mar-19
17.	903	56	Raising of deteriorated lanes and P/L CC pavement in extended lanes and construction of SW drain in JJ Cluster adjoining NH-24, Gazipur.	C09	EIUS	Under Award	17.83	28-Feb-19	-	30-Apr-19
18.	905	56	Providing and placing water storage tank, P/F wash basin and half stall urinal with some other items in Community Hall at block-11-12, Kalyanpuri.	C09	BVK	Work Completed	0.34	08-Jul-18	100%	07-Aug-18
19.	907	56	Upgradation of BVK (double storey) in JJ Basti at block-19-20, Kalyanpuri	C09	BVK	Work Completed	4.02	12-Sep-18	100%	30-Jan-19
20.	909	56	Upgradation of BVK(double storey) in JJ Basti at block-13-14, Kalyanpuri (Bus stand Khichripur)	C09	BVK	Work Completed	4.53	12-Sep-18	100%	10-Nov-18
21.	911	56	Up-gradation of BVK (duble storey) at JJ Basti block-17-21, Kalyanpuri.	C09	BVK	Work Completed	5.60	20-Oct-18	100%	18-Dec-18
22.	980	56	P/F sign boards on various vacant land pockets of DUSIB in AC-56 Kondli. (25 Nos.)	C09	GIA	Work Completed	1.49	01-Jun-18	100%	05-Jul-18
23.	959	56	P/L sewer line of 40 seater JSC at Gazipur JJ Cluster near NH-24.	C09	JSC	Work Completed	0.59	09-Jun-18	100%	07-Jul-18
24.	964	56	Providing and fixing of wall tile, floor tile, APP sheet on terrace and other some allied work in two No. JSC at Block-17-21, Kalyanpuri.	C09	JSC	Work Completed	4.53	11-Oct-18	100%	19-Dec-18
25.	923	56	Cleaning septic tank of JSC at JJ Basti(s) Block-18 Indira Camp, Kalyanpuri.	C09	JSC	Work Completed	0.34	28-Nov-18	100%	12-Feb-18
26.	946	56	P/L sewer line of 40 seater JSC at Gazipur JJ Cluster near NH-24.	C09	JSC	Work Completed	0.40	1-08-18	100%	30-Aug-18
27.	949	56	P/L sewer line of damaged portion of 88 seater at block-18, Kalyanpuri.	C09	JSC	Work Completed	0.80	20-Mar-18	100%	08-Sep-18

S.No	Temp Code New	AC No	Name of Work	Div	Scheme	Status of Work	Tendered Amt in Lacs	DOS/ Likely date of start	As on date progress (in %age) For ongoing works	Date of completion / Likely Date of Completion
28.	954	56	P/F water storage tank at roof with some allied work at JSC block-18, Kalyanpuri (73 seater and 88 seater).	C09	JSC	Work Completed	0.40	07-Oct-18	100%	22-Oct-18
29.	955	56	P/F FRP doors and frames in JSC (88 seater) code No. 56CJ1238 in JJ Basti at Block-18, Kalyanpuri.	C09	JSC	Work Completed	0.40	17-Nov-18	100%	30-Nov-18


 12/11/18